

VEHICLE INSPECTION REPORT

BN21AOW

Iveco Daily 35-120

Inspection

Serious Damage? No

Vehicle

VAT	Plus VAT
V5	To Follow
Cap Id	38809
Cap Code	IVDA23S352VDTM2 4 L

Details

Location	Bedford	Fuel Type	DIESEL	Body Style	Panel Van MWB
Reg. date	31/03/2021	GVW	3500kg	MOT Due	28/08/2027
Year	2021	Colour	WHITE	Gearbox	MANUAL
Mileage	56,403 Miles Warranted	VIN	ZCFC3358105386508	Gears	6

AD BLUE, SIDE LOADING DOOR, E/MIRRORS, AIR COMPRESSOR EQUIPMENT & 110V OUTLETS

Tyres

NSF

NSR

OSF

OSR




Spare

Features


- Front parking sensor
- Park assist camera
- Rear parking sensor
- Air conditioning
- Front electric windows

Photos





Condition Check



Damage Photos



1: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

4: Door Moulding nsr
Scuffed (Unpainted)
UpTo 100mm



5: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint

6: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



7: Qtr Panel osr
Dented
With Paint Damage

8: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK