

VEHICLE INSPECTION REPORT

PO13DYY

Daf LF 45.140

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 01/04/2013

VIN XLRAE45FF0L425122

Axle Combi 4x2

Year 2013

Body Style Box Van

Rear Suspension Steel

Mileage 884,932 Km Warranted

MOT Due 30/09/2025

Tail Lift Cantilever

Fuel Type Diesel

Cab Type DAY CAB

Colour RED

Gearbox MANUAL

COLLECTED AS NON RUNNER - CORROSION

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Cruise control
- Radio/CD
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Dented
With Paint Damage



3: Door osf
 Scratched
 Over 25mm Thru Paint



4: Door Pad osf
 Soiled
 Heavy



5: Seat Base Cover nsf
 Soiled
 Heavy

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		